

P24108.A20



C of C

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor : Stephen PALM

Certificate of Corrections Branch

Patent No. : 6,952,442

Issued: October 4, 2005

Appl. No. : 10/657,271

Filed: September 9, 2003

For : ACTIVATION OF MULTIPLE XDSL MODEMS WITH IMPLICIT
CHANNEL PROBE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate
JUL 28 2006
of Correction

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent, which is the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction. Since the error is the fault of the U.S. Patent and Trademark Office, no fee is due.

On the cover of the printed patent, at Item (56), References Cited, Foreign Patent Documents, "97149229" (found on page 2 of the cover) should be ---97/49229---. This appeared correctly on the initialed Form PTO-1449 considered by the Examiner on June 24, 2005 and attached to the Office Action mailed on July 14, 2005.

AUG 01 2006


P24108.A20

Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:

On the cover of the printed patent, at Item (56), References Cited, Foreign Patent Documents, "97149229" (found on page 2 of the cover) should be ---97/49229---.

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,
Stephen PALM

A handwritten signature in black ink, appearing to read "Bruce H. Bernstein", with a long horizontal flourish extending to the right.

Bruce H. Bernstein
Reg. No. 29,027

Steven Wegman
Reg. No. 31,438

July 26, 2006
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

AUG 01 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,952,442

DATED : October 4, 2005

INVENTOR(S) : Stephen PALM

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, Foreign Patent Documents, "97149229" (found on page 2 of the cover) should be ---97/49229---.

MAILING ADDRESS OF SENDER:

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

PATENT NO. 6,952,442

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

AUG 01 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,952,442

DATED : October 4, 2005

INVENTOR(S) : Stephen PALM

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, Foreign Patent Documents, "97149229" (found on page 2 of the cover) should be ---97/49229---

MAILING ADDRESS OF SENDER:

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

PATENT NO. 6,952,442

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

AUG 01 2006